

IECEX Quality Assessment Report: GB/SIR/QAR07.0023/08 details

QAR :	
QAR Reference Number *: (automatic numbering)	GB/SIR/QAR07.0023/08
Related QARs:	GB/SIR/QAR07.0023/03 GB/SIR/QAR07.0023/02 GB/SIR/QAR07.0023/00 GB/SIR/QAR07.0023/06 GB/SIR/QAR07.0023/01 GB/SIR/QAR07.0023/04 GB/SIR/QAR07.0023/05 GB/SIR/QAR07.0023/07
Status*:	Issued
QAR Free Reference Number*:	70008391
Audit Date*: (yyyy-mm-dd)	2014-12-09
Date of Issue*: (yyyy-mm-dd)	2015-05-05
Details of change*:	Surveillance Audit & extension to scope
Valid until*: (yyyy-mm-dd)	2015-12-24
Site(s) audited*:	Controlled Systems Limited Ryder Close Cadley Hill Swadlincote Derbyshire DE11 9EU
Issuing ExCB*:	SIR - SIRA Certification Service
Manufacturer*:	Controlled Systems Limited Ryder Close Cadley Hill Swadlincote Derbyshire DE11 9EU
Country of Manufacture*:	United Kingdom
Product information*:	PLC & radio control equipment
Protection concept*:	intrinsic safety flameproof type n Dust Optical Radiation Dust Ignition protection by Enclosure
Related IECEX Certificates: (automatic linking)	-
Related Certificates: (manual insertion)	
Related IECEX Certificates for all previous versions:	IECEX SIR 08.0032X issue: 0 [Current] IECEX SIR 08.0117X issue: 0 [Current] IECEX SIR 07.0042X issue: 1 [Current] IECEX SIR 07.0043 issue: 1 [Current] IECEX SIR 07.0042X issue: 0 [Current] IECEX SIR 09.0057 issue: 0 [Current] IECEX SIR 09.0057 issue: 1 [Current] IECEX SIR 07.0042X issue: 2 [Current] IECEX SIR 07.0043 issue: 0 [Current] IECEX SIR 08.0072 issue: 0 [Current] IECEX SIR 09.0057 issue: 2 [Current] IECEX SIR 09.0057 issue: 1 [Current] IECEX SIR 07.0042X issue: 2 [Current] IECEX SIR 09.0057 issue: 2 [Current] IECEX TSA 10.0043X issue: 0 [Current]

[IECEX SIR 10.0040X issue: 0 \[Current\]](#)
[IECEX SIR 09.0057 issue: 1 \[Current\]](#)
[IECEX SIR 07.0042X issue: 2 \[Current\]](#)
[IECEX SIR 10.0087U issue: 0 \[Current\]](#)
[IECEX SIR 10.0044X issue: 0 \[Current\]](#)
[IECEX SIR 09.0057 issue: 2 \[Current\]](#)
[IECEX SIR 10.0040X issue: 1 \[Current\]](#)
[IECEX SIR 10.0044X issue: 1 \[Current\]](#)
[IECEX SIR 10.0088X issue: 0 \[Current\]](#)
[IECEX SIR 07.0042X issue: 2 \[Current\]](#)
[IECEX SIM 12.0002X issue: 0 \[Current\]](#)
[IECEX SIR 10.0040X issue: 1 \[Current\]](#)
[IECEX SIR 10.0044X issue: 1 \[Current\]](#)
[IECEX CML 14.0002 issue: 0 \[Current\]](#)
[IECEX CML 14.0010 issue: 0 \[Current\]](#)
[IECEX CML 15.0008X issue: 0 \[Current\]](#)
[IECEX CML 15.0009U issue: 0 \[Current\]](#)

Comment:

Attachment:

Last modified: 06/05/2015 06:01:04

Copyright © IEC-IECEX 2015 , Geneva, Switzerland. All rights reserved.